

APPENDIX -XI

BUILDING SAFETY CERTIFICATE

Date: 11-03-2024
Dated:

No. PCC/103/01


Certified that the existing building Doon Valley Public School (name of the building or premises) at Garhi Cantt. Dehradun - 248003 (address) comprised of Ground basement(s) and Two (upper floors) owned/occupied by Doon Valley Public School

(name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Town & Planning (Name of Department/ Govt.) on 11-03-2024 (date of inspection) in the presence of Sanjay Joshi, 498 T/1, Dandi Garhi Cantt (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy upto classes XII (X/ XII) with effect from 11-03-2024 for a period of 5 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Number of Storeys in the building cannot be increased as the structure is safe for G+2 only.
2. If any kind of damage will happen to the RCC components of the building it should be repaired immediately under the supervision of authorised Structure Engineer.

Issued on 11-03-2024 at Dehradun by Prateek Uniyal

* Strike out whichever is not applicable.


Manager
Doon Valley Public School
Garhi Cantt., Dehra Dun.

PRATEEK UNIYAL
Ajampur Chawk,
Veterinary Hospital, Dehradun
Regn. No.: DOH-UK/G-II/ASE-4/2019

Signature with Seal : _____

Name : Prateek Uniyal

Designation : Structure Engineer

Name & Address of Department/ Office: Town & Planning

(Assistant Engineer & above officer of concerned Govt. Department only)

Note: This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.